

# EPA Notification of Hazardous Waste Site

United States  
Environmental Protection  
Agency

10460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be received by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

EPA Region 5 Records Ctr.



314697

810609

IL #112

ILS-000-001-403

## A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name ABBOTT LABORATORIES  
Street 1400 SHERIDAN ROAD  
City NORTH CHICAGO State ILL. Zip Code 60064

## B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Former Abbott Disposal  
S. of DAHRINGER RD.  
(SEE SKETCH MAP)

City WAUKEGAN County LAKE State ILL. Zip Code 60085 ✓

## C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Middle) SCHWARZ, DAVID - DIR., CORP. ENV. CONT.  
Phone (312) 937-8380

## D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From ABOUT 1950 To Year 1970

## F Waste Type: Choose the option you prefer to complete

**Option 1:** Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item 1, Description of Site.

### General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1 ☒ Organics
- 2 ☐ Inorganics
- 3 ☒ Solvents
- 4 ☐ Pesticides
- 5 ☒ Heavy metals
- 6 ☒ Acids
- 7 ☐ Bases
- 8 ☐ PCBs
- 9 ☐ Mixed Municipal Waste
- 10 ☐ Unknown
- 11 ☒ Other (Specify)

ACTIVATED SLUDGE

### Source of Waste:

Place an X in the appropriate boxes.

- 1 ☐ Mining
- 2 ☐ Construction
- 3 ☐ Textiles
- 4 ☐ Fertilizer
- 5 ☐ Paper/Printing
- 6 ☐ Leather Tanning
- 7 ☐ Iron/Steel Foundry
- 8 ☐ Chemical, General
- 9 ☐ Plating/Polishing
- 10 ☐ Military Ammunition
- 11 ☐ Electrical Conductors
- 12 ☐ Transformers
- 13 ☐ Utility Companies
- 14 ☐ Sanitary Refuse
- 15 ☐ Photofinish
- 16 ☐ Lab/Hospital
- 17 ☐ Unknown
- 18 ☒ Other (Specify)

PHARMACEUTICAL

**Option 2:** This option is available to persons familiar with Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

### Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.


000096 JUN-981

JUN 09 1981

## Notification of Hazardous Waste Site

Side Two

- Waste Quantity:**
- Place an X in the appropriate boxes to indicate the facility types found at the site.
- In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.
- In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

## Facility Type

- 1 ☐ Piles
- 2 ☐ Land Treatment
- 3 ☒ Landfill
- 4 ☐ Tanks
- 5 ☐ Impoundment
- 6 ☐ Underground Injection
- 7 ☐ Drums, Above Ground
- 8 ☐ Drums, Below Ground
- 9 ☐ Other (Specify) \_\_\_\_\_

## Total Facility Waste Amount

cubic feet UNKNOWNgallons UNKNOWN

## Total Facility Area

square feet \_\_\_\_\_

acres 15 A

## G. Known, Suspected or Likely Releases to the Environment:


Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment

☐ Known ☒ Suspected ☐ Likely ☐ None

**Note:** Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

## H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.



## I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

PURCHASED BY THE NSSD FROM ABBOTT IN 1971 FOR CONSTRUCTION OF TREATMENT FACILITIES, THIS SITE WAS USED BY ABBOTT FOR SOME 20 YEARS (1950-1970) TO DISPOSE OF BY LAND SPREADING AND BURIAL VARIOUS PROCESSING WASTES AND EXCESS ACTIVATED SLUDGE FROM MANUFACTURING AND WASTEWATER TREATMENT OPERATIONS OF THE ABBOTT LABORATORIES PLANT AT NORTH CHICAGO, ILLINOIS.

## J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name

David Schularz

TITLE

DIRECTOR, CORP. ENVIR. CONT.

City

State

Zip Code

Signature

Date

☐ Owner, Present☒ Owner, Past☒ Transporter☐ Operator, Present☒ Operator, Past☐ Other

FACILITY ID NUMBER										COMPANY NAME																			
1LS0000001403										Abbott Labs																			
COMPANY ADDRESS															CITY					STATE ABBREV.					ZIP CODE				
CONTACT PERSON'S NAME/TITLE																				TELEPHONE NUMBER (INCLUDE AREA CODE)									
																				-									

[illegible]

D-539


**ABBOTT**  
Abbott Laboratories  
North Chicago, Illinois 60064

**CERTIFIED MAIL**

No. 536320

RETURN RECEIPT REQUESTED  
FEE PAID

US EPA Region 5  
Sites Notification  
Chicago, Illinois 60604



CERTIFIED MAIL  
RETURN RECEIPT REQUESTED